

Community Update

March 2018



Progress update

Stage 2 (Northern part of the site) of the CSIRO Highett demolition was completed in mid-March. This area of the site will now be fenced off and maintained in a tidy state until the remainder of the site demolition activity is complete.

Stage 3 of the project (Southern part of the site) is on track and progressing well. A total of 15 buildings in the southern portion of the site have been demolished to slab level, with slab removal commencing on site since our last newsletter.

CSIRO appreciates your understanding and patience while these important works are being carried out.

Tree protection

CSIRO understands that the trees are highly valued by the local community and we have

committed to avoiding tree removal where possible. CSIRO regularly meets with the independent arborist engaged by Bayside City Council, with their next site visit scheduled for mid-April, 2018.

Keeping you safe

CSIRO is committed to keeping its staff, contractors and the local community safe during the demolition and clean-up project. All work is being carried out in line with WorkSafe requirements and the relevant Australian Standards. CSIRO has engaged an independent licenced asbestos assessor who will continue to monitor the removal of hazardous materials. The various dust and noise monitoring points throughout the southern portion of the site have been identified on the below plan.


Keeping you informed

Thank you for your patience while we

complete the demolition works. We will be providing you with monthly newsletter updates as the work progresses. For more information, you can also visit our website: wp.csiro.au/highettworks/.

Contact details

If you have any questions or concerns please contact us by phone on 1300 363 400 (9am to 5pm) or email highettworks@csiro.au.



Demolition of Building 42

Site Plan

37 Graham Rd, Highett VIC 3190

